

Martha E. Michels
Chief Safety Officer

ESH&Q Section
P.O. Box 500, MS 119
Kirk Road and Pine Street
Batavia, Illinois 60510-5011
USA
Office: 630.840.3511
martha@fnal.gov

Date: September 4, 2018
To: Timothy I. Meyer, COO
From: Martha Michels *mm*
Re: FESHM 5031.4 – Inspection and testing of Relief Systems
FESHM 5032.1 – LN₂ and LAr Dewar Installation and Operation Rules
FESHM 8021 – Chemical and Radioactive Waste Management

FESHM 5031.4 has been updated as follows:

- Added information about paying attention to accumulation of vacuum grease on tested/inspected relief devices in Section 4.2.

FESHM 5032.1 has been updated as follows:

- Additional rules for vendor owned stationary dewars concerning signage and relief inspections added as TA section 6.8
- Scope edited for clarity

FESHM 8021 has been updated as follows:

- Added organizational responsibilities in Section 3.2
- Added generator requirements in Section 3.4
- Added requirement to provide correct hazardous waste code in Section 4, item #1

These chapters have gone through the labwide review process, all comments have been addressed, and they are ready for your review and approval. The chapters have been sent to you and Lisa Vega electronically. If paper copies are required, you may either print them out or contact Lisa.

Please return this signature page to T.J. Sarlina at MS 119 after Directorate approval.

Recommended for Approval:



Timothy I. Meyer, COO

9/4/2018

Date

Approved:



Nigel S. Lockyer, Director of Fermilab

9/12/18

Date